



**US Army Corps
of Engineers®**

HUNTINGTON DISTRICT

ATTN: CELRH-DE
502 8TH STREET
HUNTINGTON WV 25701-2070
HTTP://WWW.LRH.USACE.ARMY.MIL/

DATE: 03/16/2018

POC: Kent C. Browning
Chief, Waterways
Section
304-399-5239

NOTICE NUMBER: 8583

LOCAL NUMBER: 18-10
WATERWAY: OHIO RIVER

EFFECTIVE: 03/16/2018 15:07 thru 03/30/2018 15:00
EDT

SHOALING CONDITIONS

ROBERT C. BYRD LOCKS AND DAM

OHIO RIVER, MILE 279.2

Notice is given that due to recent flooding and receding water levels on the Ohio River, shoal conditions exist in the lower approach channel at Robert C. Byrd Locks and Dam, Ohio River, mile 279.2.

The most recent survey, completed 16 March 2018, is attached to this notice and will be available at the following link:

<http://www.lrh.usace.army.mil/Missions/Civil-Works/Navigation/>

Mariners are urged to check the channel depth surveys, monitor lower gage readings, and contact the lockmaster via marine radio on channel 13 for more information.

An additional notice will be issued containing dredging information for this site when available.

//signed//

DALE A. SMITH
Acting Chief, Technical Support Branch