



**US Army Corps  
of Engineers®**

HUNTINGTON DISTRICT

ATTN: CELRH-DE  
502 8TH STREET  
HUNTINGTON WV 25701-2070  
HTTP://WWW.LRH.USACE.ARMY.MIL/

**DATE:** 03/08/2019

**POC:** Kent C. Browning  
Chief, Waterways  
Section  
(304)399-5239

**NOTICE NUMBER:** 9803

**LOCAL NUMBER:** 19-07  
**WATERWAY:** OHIO RIVER

**EFFECTIVE:** Immediately thru Until Further Notice  
EDT

---

**SHOALING CONDITIONS**

**ROBERT C. BYRD LOCKS AND DAM**

**OHIO RIVER, MILE 279.2**

Notice is given that due to recent flooding and receding water levels on the Ohio River, shoal conditions exist in the lower approach channel at Robert C. Byrd Locks and Dam, Ohio River, mile 279.2.

The most recent survey, completed 07 March 2019, is attached to this notice and will be available at the following link:

<https://www.lrh.usace.army.mil/Portals/38/docs/navigation/SHOALING%20CONDITIONS.pdf?ver=2019-03-08-134529-890>

Mariners are urged to check the channel depth surveys, monitor lower gage readings, and contact the lockmaster via marine radio on channel 13 for more information.

An additional notice will be issued containing dredging information for this site when available.

//signed//

PETER K. DODGION  
Chief, Technical Support Branch